


MODEL	YEAR
Cordoba	75-79
Dakota V-8	98-02
Durango	97-02
Fifth Avenue	73-81
Fury	73-81
Imperial	74-75
Newport	73-81
New Yorker	73-81
Charger	74-76
Monaco	75-85
Polara	70-74
Ram	82-03
Ramcharger	74-96
Trailduster	74-90
B350	84-Present
D200 (Rear)	66-98
D300, D350	74-Present
W100, W150	74-Present
W200, W250	74-Present



- Irregular Cover
- 12 Holes
- 12 Bolt
- 9.25" Diameter Ring Gear
- 1.877" Diameter Pinion
- 29 Splines

RATIO	PART NO.	TEETH
3.55	49-0078-1	39-11
3.91	49-0080-1	43-11
4.10	69-0220-1	41-10
4.56	69-0222-1*	41-9

* Requires Special Cross Shaft Pin.

For Maximum Protection and Performance use Part # LUBE (pg 125)

RICHMOND GEAR Synthetic Gear Oil

INSTALLATION KIT/HALF KIT

PART NO.
83-1041-1
83-1041-M
83-1041-B Half-Kit

SPOOLS

PART NO.	SPLINE	CARRIER
Contact Factory		

SPOOL BEARING KIT

PART NO.
Contact Factory



Always in stock at your local RICHMOND distributor